



Service Bulletin SB21000008
NEW ECB – CLOUD SEVEN & LULLABY
NUOVA ECB – CLOUD SEVEN & LULLABY

Service Bulletin SB21000008

Problem: Hood does not work with remote control.
Problema: La cappa non funziona con il telecomando.

Solution: Replace the electronic board.
Soluzione: Sostituire la scheda elettronica.

CLOUD SEVEN



PRF	12NC	Old code	New code
PRF0142094A	208355406009	ECB0151723	ECB0168964



ECB0168964

LULLABY



PRF	12NC	Old code	New code
PRF0146225	208355404956	ECB0151723	ECB0171789
PRF0146226	208355404957	ECB0151723	ECB0171789



ECB0171789

